



Photo 1 – View of wreckage laying inverted in the woods



Photo 2 – View from the front of the inverted wreckage



Photo 3 – View of right wing separated and lying next to the fuselage



Photo 4 – View of the separated right wing and fuselage from the left rear of the aircraft



Photo 5 – View of the inverted right wing and landing gear



Photo 6 – View of right wing and center section wing spar



Photo 7 – View of the empennage and tailwheel



Photo 8 – Close-up view of rudder and right elevator



Photo 9 – View of the separated left wing in the woods



Photo 10 – View of the bottom of the fuselage’s center section



Photo 11 – View of the aircraft’s propeller and the crushed engine cowling



Photo 12 – View of propeller blade



Photo 13 – Close-up view of the propeller blade



Photo 14 – View of damage to the blade tip



Photo 15 – View of the leading edge of the propeller blade



Photo 16 – View of the crushed propeller spinner and other propeller blade



Photo 17 – View of the other propeller blade



Photo 18 – View of the other propeller blade tip



Photo 19 – View of the blade face of the other propeller



Photo 20 – View of fuel selector