



Photo 1 – View of wreckage in a cornfield



Photo 2 – View of the left side of the aircraft wreckage in a cornfield



Photo 3 – View of the left side of the wreckage



Photo 4 – View of the left wing and broken flaperon attach points



Photo 5 – View of the left wing and broken flaperon



Photo 6 – View of the top of the cabin and inboard section of the right wing



Photo 7 – View of the right wing and flaperon



Photo 8 – View of the right wing and flaperon attach points



Photo 9 – View of the broken propeller blades at the accident site



Photo 10 – View of the propeller and the front of the aircraft




Photo 11 – View of the engine and propeller



Photo 12 – View of cockpit and control sticks



Photo 13 – View of bottom of the pilot's control stick



Photo 14 – View of the fractured flaperon control tube



Photo 15 – View of the flight control tubes



Photo 16 – View of the control tube attachment to the left flaperon




Photo 17 – View of the flaperon control tube and control arm



Photo 18 – View of the broken outboard left wing flaperon attach point