



Photo 1 – Airplane Wreckage at Accident Site Right Side



Photo 2 – Airplane Wreckage at Accident Site Left Side



Photo 3 - Airplane Wreckage in Hangar after Recovery



Photo 4 - Closeup of Engine After Recovery




Photo 5 - Loose B-Nut Fitting Observed During Engine Examination



Photo 6 - Closeup of Loose B-Nut Fitting




Photo 7 - Engine Running in Test Cell