



Photo 1 – The unregistered gyroplane. Note absence of ground scars, only impact crater, consistent with no forward velocity



Photo 2 - Rear view of gyroplane, showing Subaru engine and pusher-type propeller.



Photo 3 - Close-up of the engine and propeller.