



Photo 1 – The ground scar aligned on magnetic course of 197°.



Photo 2 - Debris field extends towards treeline.



Photo 3 - Propeller blade assembly.



Photo 4 - Debris field continues down hill into creek bed.



Photo 5 – Second propeller assembly.



Photo 6 – The empennage.



Photo 7 – Cockpit and cabin area.



Photo 8 – Left engine.



Photo 9 – Right engine.



Photo 10 – Wreckage layout, right front.



Photo 11 – Wreckage layout, left front.



Photo 12 – Wreckage layout, rear view.