



Photo 1 – View of the wreckage from the front of the aircraft



Photo 2 – View of the left side of the aircraft



Photo 3 – View of the wreckage from the rear of the aircraft



Photo 4 – View of the wreckage from the right of the aircraft



Photo 5 – View of one of the propeller blades that is visible at the accident site



Photo 6 – View of the rear wing spar separated from the middle wing section



Photo 7 – View of the left side of the empennage



Photo 8 – Close-up view of the rudder trim tab



Photo 9 – View of the left main gear collapsed to the rear



Photo 10 – View of the cockpit instruments



Photo 11 – View of the fractured plywood floorboards under the rear pilot's seat



Photo 12 – View of one of the propeller blades



Photo 13 – View of some blade tip damage



Photo 14 – View of the damage to the other blade



Photo 15 – View of the rear of the engine




Photo 16 – View of the top of the engine and propeller