




**Photo 1 – The tail boom being recovered from the waters of West Bay, Galveston, Texas.**



**Photo 2 – Bottom portion of fuselage and landing skid after recovery from West Bay.**



**Photo 3 – Forward portion of wreckage laid out at T&T Marine Salvage, Teichman Point, Galveston, Texas.**



**Photo 4 – Aft portion of wreckage being laid out at T&T Marine Salvage, Teichmam Point, Galveston, Texas.**




**Photo 5 – Measuring the angle of a main rotor blade strike at the aft baggage compartment-tail boom.**



**Photo 6 – Main rotor blade strike on the left side of the engine.**



**Photo 7 – Aft tail boom, tail rotor hub, and tail rotor blades were undamaged.**



**Photo 8 – Main rotor hub bore evidence of torsional overload and mast rubbing.**