



Photo 1 – Green position light lens fragments were found at the beginning of a 35-foot long ground scar aligned on a magnetic course of 121°.



Photo 2 – Water-filled impact crater.



Photo 3 – The debris path extended 250 feet on a magnetic course of 130°. Note a propeller blade next to the impact crater.



Photo 4 – The left wing.



Photo 5 – The right wing.



Photo 6 – The aft fuselage and empennage.



Photo 7 – The cockpit and cabin area.



Photo 8 – The engine. Note all three composite propeller blades have been severed.