



Photo 1 – View of main wreckage from front



Photo 2 – View of wreckage from right



Photo 3 – View of wreckage from left




Photo 4 – View of engine during disassembly



Photo 5 – View of engine sump showing metal found on disassembly




Photo 6 – View of split engine case showing bearing as found on disassembly



Photo 7 – Close up showing shifted bearing




Photo 8 – Close of up shifted bearing after crankshaft removal