



Photograph 1 – Aerial View of Debris Field (Provided by Ainsworth Fire Department)



Photograph 2 – Initial Impact Point and Left Engine



Photograph 3 – Left Engine and Propeller Blades



Photograph 4 – Debris Field



Photograph 5 – Main Wreckage



Photograph 6 - Empennage