



Photo 1 – Engine with multiple breaches in crankcase




Photo 2 – Crankshaft with discolored connecting rods and bearings




Photo 3 – Camshaft displaced from crankshaft



Photo 4 - 6th order counterweight connecting pin lodged in crankcase



Photo 5 – 6th order counterweight and debris from oil pan