



RECORD OF CONVERSATION

Arnold W. Scott
Senior Air Safety Investigator
Central Region

Date: October 4, 2017
Person Contacted: Victor Lopez
NTSB Accident Number: CEN17LA003

Narrative:

During a telephone conversation FAA Inspector Victor Lopez of the San Antonio Flight Standards District Office, he stated that the pilot, Richard Hornbuckle, told him and other inspectors that the engine lost power when the airplane was ½-mile from runway 35 and a forced landing ensued. During the forced landing, both wings were torn off the aircraft and it caught fire. He pulled his daughter from the burning wreckage and walked to a nearby rural residence.