



Photo 1 – Supplied photo looking at the front of the airplane. Propeller tips are bent rearward and the spinner is crushed.



Photo 2 - Supplied close-up photo looking at the tailwheel assembly. The tailwheel is not present.



Photo 3 - Supplied close-up photo looking at the tailwheel assembly. The tailwheel is not present.



Photo 4 - Supplied photo looking at left wing tip. The outboard wing section exhibits upward deformation.



Photo 5 - Supplied photo looking at left wing tip. The outboard wing section exhibits upward deformation.



Photo 6 - Supplied close-up photo looking at left wing tip. The outboard wing section exhibits upward deformation.



Photo 7 - Supplied close-up photo looking at left main landing gear tire.