



Photo 1 – Damage to left horizontal stabilizer and elevator



Photo 2 – Missing landing gear door