



Figure 1: Photo of a “Beech Aircraft Corporation” label with part number “95-810017-23 ECH,” serial number “94-B-479”.



Figure 2 – Photo of a “Cruiseair Aviation, Inc.” label with no part or serial number annotated.



Figure 3 – Photo of a “Beechcraft Rebuilt Part” label with part number “95-810017-23 ECH,” serial number “94-B-479”.



Figure 4 - The sector gear teeth were partially sheared and were bound with worm gear teeth resulting in interference.



Figure 5 - The photo depicts partial shearing of the sector gear teeth.