

Sauer Aaron

Subject: FW: N6330B Accident at Skiatook, OK CEN17LA123

Aaron,

Below is the pilot statement in reference to Cessna 182, N6330B accident that occurred at Skiatook, Oklahoma.



Rakesh P. (Rocky) Patel
Aviation Safety Inspector
FAA Flight Standards District Office
1300 S. Meridian Ave, Suite 601
Oklahoma City, Oklahoma 73108

From: Steve Wilemon
Sent: Monday, March 13, 2017 8:30 PM
To: Patel, Rocky (FAA)
Subject: N6330B

Rocky, here is my summation of what happened. Date 3/13/2017.

Had done pre flight on the plane, was in taxi to runway 36 for a warm up flight prior to customers. While in taxi, something caused the plane to pull hard right, left rudder or left brake had no effect, plane was headed into the drainage ditch on the west side of the taxi way. Pulled throttle to full back & lean to full lean to stop the plane. Went into the ditch.

Upon review of the scene after, there was tire tracks on the taxiway from the right main gear, and heavy indentation in the grass where the right gear had gone, and not for the left gear.

I am still waiting on the pictures to download to my email account, will send as soon as I receive them.

Steve Wilemon