



Photo 1 – View of gyroplane on the side of a ditch at the accident site



Photo 2 – View of the front of the gyroplane.



Photo 3 - View of the left cockpit/cabin door of the gyroplane



Photo 4 - View of the main rotor blade which separated from the mast



Photo 5 - View of the power line that was hit by the gyroplane



Photo 6 - View of the gyroplane's data plate




Photo 7 - View of the cockpit's power quadrant



Photo 8 - View of the bottom of the engine




Photo 9 - View of the bottom of the engine




Photo 10 - View of the right side of the engine (looking aircraft forward)



Photo 11 – View of the left side of the engine (looking aircraft forward)



Photo 12 – View of the Wastegate Actuator



Photo 13 – View of the left carburetor and airbox



Photo 14 - View of airbox and black ignition boxes



Photo 15 – View of the left coolant radiator (Intercooler)




Photo 16 – View of right Bing carburetor




Photo 17 – View of the exhaust outlet



Photo 18 – View of the manifold pressure probe




Photo 19 - Manifold pressure probe installation




Photo 20 – View of engine with turbocharger parts identified