



Photo 1 – N457PH after precautionary landing at Grand Bay Receiving Station near Venice, Louisiana.




Photo 2 – Tail rotor blade with tip cap missing.



Photo 3 – Crack in tail rotor gear box housing.




Photo 4 – Cracks in the tail boom support casting.



Photo 5 – Sheared studs removed from tail rotor gear box housing.