

Lemishko Alex

From: Crookshanks Clinton
Sent: Thursday, October 26, 2017 9:58 AM
To: Lemishko Alex
Subject: elevator control rod

Alex,

I took a look at the elevator control rod. There is no indication of any pre-existing failure on the fracture surface. It is consistent with overload. The deformation of the rod is indicative of a bending failure of the rod.

Clint Crookshanks
Aerospace Engineer (Structures)
National Transportation Safety Board
[REDACTED]