



Photo 1 – Aircraft at Accident Site



Photo 2 – Fractured Right Elevator Control Rod at Accident Site



Photo 3 – Left and Right Elevator Control Rods