



Photo 1 – View of the helicopter looking forward from its right rear side.



Photo 2 - View of the helicopter looking towards its left side with the truck and the splintered wooden blade present.



Photo 3 - View of the separated rotor mast.




Photo 4 - View of the fractured transmission case.




Photo 5 - Close-up view of the bent rotor mast,



Photo 6 - Close-up view of the truck cab and water tank damage.



Photo 7 - View of random splinters in the area..



Photo 8 - Close-up view of a section of main rotor blade spar.



Photo 9 - View of recovered main rotor blade splinters.



Photo 10 - View inside the rotor mast.