



Photo 1 – Airplane at Accident Site



Photo 2 – Hole Adjacent to Number 4 Cylinder



Photo 3 – Removed Engine Prior to Examination




Photo 4 – Vacuum Pump Gasket as Discovered (Red Arrow Indicates Exposed Oil Orifice)