



Photo 1 – N571UJ on runway 36, shortly after the accident.



Photo 2 – Damage to the gyroplane included the main rotor blades and propeller blades.



Photo 3 – N571UJ after being placed back on its landing gear.