



Photo 1 – View of Lycoming Engine



Photo 2 – View of Fractured Connecting Rod



Photo 3 – View of Connecting Rod Bushing