



Frontal view, note position of engine



Boot cowl crushed



Firewall and all supporting structure crushed inward



Right side view



Right side view




Right side



**Support for lower wing
attach fitting**



**Buckle in fitting support
structure**



Left side



Left side view



Keel and Support structure



**All support structure will
require replacement**