



Photo 1 – View of the helicopter wreckage at the accident site.



Photo 2 - View of the helicopter engine, transmission, and mast.



Photo 3 - View of a section of tailboom that was consumed by fire.



Photo 4 - View of skid and crosstube components.




Photo 5 - View of the tailboom, main rotor blade, and ground scars.



Photo 6 - View of the main rotor blades and mast.



Photo 7 -



Photo 8 - View of the wreckage below the powerlines.



Photo 9 - View of the helicopter wreckage at the accident site.



Photo 10 - View of the aft section of tailboom and tail rotors.



Photo 11 - Close up view of the tail rotor drive shaft.



Photo 12 - View of the separation of the aft section of tailboom.



Photo 13 - View of a skid tip with a semicircular witness mark.



Photo 14 - View of a crosstube with a witness mark and an exemplar section of powerline.



Photo 15 - View of a tail rotor blade with its liberated blade tip.



Photo 16 - Side view of a tail rotor blade with its liberated blade tip.



Photo 17 - View of a tail rotor blade with an exemplar section of powerline.



Photo 18 - Powerline personnel measuring the height of the powerline at the accident site.




Photo 19 - View from the witness location to the powerlines.



Photo 20 - Close-up view of a powerline with a separated strand.