



Photo 1 – Main wreckage



Photo 2 – Main wreckage



Photo 3 – Tree limb showing prop slash




Photo 4 – Engine during examination



Photo 5 – Vacuum pump during examination