



Photo 1 – Airplane wreckage



Photo 2 - Wing, main landing



Photo 3 – Left side, 3-Bladed propeller



Photo 4 – Left side engine: Fire and impact damage

Photo courtesy of Lycoming



Photo 5 – Turbo charger

Photo courtesy of Lycoming