

View looking south


Structure Arm

Static Line

Repair was to move static line
back onto the top of the structure
arm; helicopter approached from south

Helicopter


South view of the accident site with the helicopter main wreckage




Static line resting on structure arm


Damage to 2 of the conductor lines

Photo shows the static line resting on the structure line and the two damaged conductor lines.





Close up view of the structure arm two days prior to the accident.



Structure arm after the accident showing a missing bracket and damage under top plate.



Structure arm after the accident showing a missing bracket and damage under top plate.

Helicopter on right side – this photo taken after the helicopter was rolled to remove fatal line worker.






View of aft left side showing damage to the skid shoe bolt and paint scrapes.



View of right aft skid showing no damage.



View of harness connection (cut by rescue personnel) for fatal line worker – all connections were correct.