

Gregory D. Boaz

League City, TX. 77573

N3896P P-210 Airframe SN P21000071
Engine IO550P6B SN 1009462

Engine Timeline of Events

07-21-2003	Teledyne Continental Issued Service BulletinSB 03-4
11-15-2013	Continental Motors Rebuilds Engine IO550P6B SN 1009462 with wrong dip stick
04-22-2014	Engine installed in aircraft (0 hrs.)
02-04-2015	Engine removed from aircraft due to prop strike (53.9 hrs.)
04-30-2015	Engine teardown & inspection by Western Skyways due to prop strike (53.9 hrs.)
07-10-2015	Engine re-installed in aircraft after prop strike inspections/repairs (53.9 hrs.)
07-10-2015	Annual Inspection (53.9 hrs.)
01-29-2018	Annual Inspection (65.0 hrs.)
04-18-2018	Pre-purchase inspection (66.5 hrs.)
05-06-2018	Engine eats dip stick on flight from KRVS to KLVJ (76.8 hrs.)

