



Photo 1 – View of Wreckage from Left Side



Photo 2 – View of Wreckage from Rear



Photo 3 – Left Wing Leading Edge Crushing



Photo 4 – Right Wing Leading Edge Crushing



Photo 5 – Right Wing Leading Edge Crushing



Photo 6 – Left Wing Leading Edge Crushing



Photo 7 – Left Wing Leading Edge Crushing