



DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION
REPORT OF AIRCRAFT ACCIDENT
(Continuation Sheet)

REPORT DATE

September 17, 2018

REPORT NO.

18-001-DTS-FCT

NAME OF REPORTING FACILITY

Destin FCT (DTS)

14. CHRONOLOGICAL SUMMARY OF FLIGHT

August 30, 2018

ALL TIMES BELOW ARE COORDINATED UNIVERSAL TIME
UNLESS OTHERWISE SPECIFIED

- 1528 Eglin Approach Control (VPS) called Local Control (LC) and provided information that N1876L was an IFR inbound 12 miles northwest for the RNAV approach to Runway 14. LC acknowledged.
- 1531 VPS advised LC that N1867L was VFR. LC acknowledged. LC called N1876L and requested a position report.
- 1532 N1876L reported 2 miles out for Runway 14 to LC.
- 1533 VPS requested LC to confirm N1876L had Destin and Eglin in sight. LC relayed to VPS the pilot reported 2 miles out. VPS advised LC the aircraft was over Eglin at two hundred feet. LC called N1876L and requested the aircraft's position.
- 1534 LC called N1876L. N1876L did not respond.
- 1535 VPS advised LC the aircraft crashed. Ground Control (GC) acknowledged.

No More Follows