



Photo 1 – View of airplane in the bean field (FAA Photo)



Photo 2 – View of minor damage to the right wing (FAA Photo)



Photo 3 – View of the hole in the crankcase (CM Photo)



Photo 4 – View of damage to the No. 2 piston connecting rod (CM Photo)



Photo 5 – View of No. 2 main bearing (CM Photo)




Photo 6 – View of No. 2 main bearing (CM Photo)




Photo 7 – View of No. 3 main bearing (CM Photo)




Photo 8 – View of No. 3 main bearing (CM Photo)



Photo 9 – View of No. 2 and No. 3 main bearings (CM Photo)



Photo 10 – View of one of the missing induction riser bolts (CM Photo)



Photo 11 – View of the crankshaft gear and the safety wire (CM Photo)