



Photo 1 – Airplane landed gear up in the grass leading to the runway



Photo 2 – Accident airplane parked on the ramp



Photo 3 – Damaged left elevator



Photo 4 – CRM 2100 installed in the instrument panel




Photo 5 – Google Earth overview with flight track and PWK



Photo 6 – Google Earth overview with flight track and C81



Photo 7 – Engine data plot




Photo 8 – Engine data plot