



RECORD OF CONVERSATION

Aaron M. Sauer
Aviation Accident Investigator
Central Region

Date: November 27, 2017
Person Contacted: Student Pilot – Eduardo Segovia
NTSB Accident Number: CEN18LA040

Narrative:

During a telephone call, the student pilot reported that his airplane preflight, engine run-up, and takeoff were normal with no anomalies noted. About 15 minutes into his solo cross-country flight, the engine lost total power, and he performed a forced landing to a mesquite tree covered area. During the forced landing, the airplane impacted a power line and mesquite trees.

The student pilot reported that an engine oil change had been done about 10 hours prior to the accident.