



Photo 1 – Front quartering view of the right wing and fuselage.



Photo 2 - Rear quartering view of the right wing, empennage, and fuselage.



Photo 3 - View of the separated left wing and empennage.




Photo 4 – Close-up view of removed engine accessories and recovered fuel.



Photo 5 - View of removed engine accessories and recovered fuel.



Photo 6 - View of fittings from the left fuel tank that exhibits staining.