



Photo 1 – Open field where the airplane landed (Pilot photo)



Photo 2 – Photo of the airplane after the accident (Pilot photo)



Photo 3 – Bent engine mount (Pilot photo)



Photo 4 – Photo of the carburetor (Pilot photo)



Photo 5 – View of carburetor venturi (Pilot photo)



Photo 6 – View of black carbon in engine exhaust (Pilot photo)