



Photo 1 – Accident Site



Photo 2 – Close-up of Damage to Structure at Nose Wheel Strut