



Photo 1 – Right Side Horizontal Stabilizer Leading Edge Damage



06/11/2018 09:05

Photo 2 – Closeup of Leading Edge Damage