



Photo 1 – View of fire damage to the right wing (FAA Photo)



Photo 2 – Closeup view of fire damage to the right wing (FAA Photo)



Photo 3 - Closeup view of fire damage to the right wing (FAA Photo)



Photo 4 – View of the fire damage to the bottom of the wing (FAA Photo)



Photo 5 – View of the right wingtip and navigation light and wing strobe (FAA Photo)



Photo 6 – View of soot and fuel stain under the wing near navigation light (FAA Photo)



Photo 7 – View of fuel stains on the bottom side of the right wing (FAA Photos)



Photo 8 – View of soot near the right navigation light (FAA Photo)



Photo 9 – View of the fire damage to the inside of the right wing (FAA Photo)



Photo 10 – View of the fire damage to the inside of the right wing (FAA Photo)



Photo 11 - View of the fire damage to a line in the right wing (FAA Photo)



Photo 12 - View of the fire damage to the inside of the right wing (FAA Photo)



Photo 13 – View of inside of the wingtip near navigation light (FAA Photo)



Photo 14 – View of the wiring wrapped in electrical tape (FAA Photo)



Photo 15 - View of the wiring wrapped in electrical tape (FAA Photo)