



Photo 1 – View of the helicopter in the residential community (courtesy of the flight instructor).



Photo 2 – View of the helicopter in the residential community (courtesy of the flight instructor).



Photo 3 – View of the helicopter recovered to the operator’s facility.



Photo 4 – View of the substantial damage to the tail boom.



Photo 5 – View of the substantial damage to the vertical stabilizer.



Photo 6 – View of the impact damage to the tail rotor blades.