



Photo 1 – Overhead Figure of Wreckage Position



Photo 2 – View of Wreckage Right Side



Photo 3 – View of Wreckage Left Side



Photo 4 – View of Engine and Propeller with Chordwise Damage