

From: Chip Cotton [REDACTED]
Sent: Thursday, July 19, 2018 9:35 PM
To: Scott Arnold [REDACTED]
Subject: RE: Your accident of 07/14/18

It was a fatigue failure. Many landing cycles and not enough stiffness and material strength of the landing gear shock cord truss.

From: Scott Arnold [REDACTED]
Sent: Thursday, July 19, 2018 4:28 PM
To: Chip Cotton
Subject: RE: Your accident of 07/14/18

Why did the landing gear fail? Was it corrosion? Pre-existing fatigue crack and overload?