



The National Transportation Safety Board

Office of Aviation Safety
Central Region
Memorandum for the Record
FAA Inspector Findings
CEN18LA281
Shreveport Louisiana
July 19 2018

The FAA inspector reported the following examination findings:

There were no anomalies with the airframe or fuel system. Examination of the engine revealed that the output shaft of the vacuum pump was sheared.

Alexander Lemishko



Senior Air Safety Investigator
NTSB Central Region Aviation