



ENGINE DATA MONITOR INFORMATION

Michael J. Folkerts
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN18LA302

The J.P. Instruments EDM-700 was downloaded at the manufacturer location, with oversight by the NTSB investigator. A review of the data revealed the following information:

- The power loss events that occurred during both flights and on the ground were consistent with a loss of fuel supply to the engine.
- Fuel consumed was about 36 gallons when all the power loss events occurred.
- Based on 37 gallons usable for each tank, the right tank was at half and the left tank was at half (about 19 gallons) when each of the power loss events occurred.