



Photo 1 – Image of an exemplar pivot sprinkler system.



Photo 2 - Image sent by the pilot's family member of the pivot sprinkler system near the accident site that exhibits damage to its outboard section.