



Photo 1 – Helicopter Wreckage at Accident Site



Photo 2 – Lower Coupling Drive Shaft, Forward End