



Photo 1 – Damage Overview (Photo from Pilot)



Photo 2 – Left Wing (Photo from Pilot)



Photo 3 – Empennage Damage (Photo from Pilot)