



Photo 1 – N956X lies inverted in an open muddy field near Opelousas, Louisiana.



Photo 2 – Rudder and vertical stabilizer were crushed when the airplane overturned.



Photo 3 – Both upper wings sustained damage in the accident. This is the left upper wing leading edge.