



Photo 1 – View to the east along Voss Road. Struck vehicles are also visible.



Photo 2 – N247F in the median on Voss Road.



Photo 3 – Severed empennage.



Photo 4 – The nose of the airplane and spilled hydraulic fluid.



Photo 5 – The spark plugs after removal from the engine. Note the damage to plugs 1 and 2.



Photo 6 – Damage to cylinder 1.



Photo 7 – Damage to piston 1. Note embedded valve fragment.



Photo 8 – Damage to pistons 2 and 3. Note embedded valve fragments.



Photo 9 – Damage to pistons 4 and 5. Note embedded valve fragments.



Photo 10 – Damage to piston 6. Note embedded valve fragment.



Photo 11 – Bent no. 1 valve stem tip caused by piston and combustion chamber contact, and most probably contributed to no. 1 intake valve failure.